www.elkproducts.com
techsupport@elkproducts.com
(800) 797-9355

ElkRP Release Notes

11/16/2026, Version 3.0.11

- Removed ability to view Operator passwords for added security
- Made improvements to data processing during firmware updates

10/21/2026, Version 3.0.7

- Added support for DDNS service configuration in the M1XIP Setup
- Corrected issue preventing completion of bootware update on older M1XEPs
- Made improvements to data processing during firmware updates
- Corrected issue with missing data on the Find M1XIPs page.
- Prevent the Network Adapter selection from being changed while the M1XEP or M1XIP Setup window is open.
- The port field on the account details page is automatically populated with the configured non-secure port when "Connect Non-Secure" is checked, or the configured secure port when it is unchecked.

10/5/2026, Version 3.0.5

- Corrected issue that may prevent or cause errors when connecting to M1EZ8 systems
- Corrected issue causing Zone Definitions error when connecting to M1EZ8 systems

9/16/2026, Version 3.0.0

- Added support for the ELK-M1XIP M1 Network (IP) Communicator
- Support for Remote Communication to XIP through the ElkConnect Proxy
- Support for Email Notifications through ElkConnect
- Support for Time Synchronization through ElkConnect

NOTE: ElkConnect proxy, email, and time sync features do not require an ElkConnect login and do not incur any fees.